

Ownership Key:  
 C/T = City or Town  
 P = Private  
 S = State  
 M = Municipal

Town of New Marlborough



Town of New Marlborough				Ground Cutting	Trimming	House #	Owner	Dia.	Species	# Stem	Defect Condition	GYPSY MOTH DAMAGE - INSERT "Y"	Work Proposed	Comments	EVM or HTM
Site ID	Street Name	Location	Pole #												
Nationalgrid EVM Program															
EVM/HTM Work List															
Circuit #: 1109w1															
RR336	Mill River Great Barrington Rd		116-115			1633	T	25	Maple		Decline		Remove		HTM
RR336	Mill River Great Barrington Rd		114-113			1633	T	38	W.Pine		Storm Damage		Remove		HTM
RR338	Mill River Great Barrington Rd		102-101			Lot	T	21	Maple		Decline		Remove		HTM
RR339	Mill River Great Barrington Rd	AF	97-96			1441	T	31	Maple		Decline		Remove		HTM
RK348	Hartsville New Marlboro Rd	AF	138-137			Lot	T	22	Oak		Base decay		Remove		HTM
RK351	Hartsville New Marlboro Rd	AP	129			21 Corashire	T	60	W.Pine		Decay/cavities		Remove		HTM
RR341	Adsit Crosby Rd	AF	6-7			Lot	T	38	W.Pine		Storm damage		Remove		HTM
RK354	Hartsville New Marlboro		108-107			Lot	T	43	White Pine		Rotted front lead		Trim	remove front lead	HTM
RK358	Hartsville New Marlboro	AF	90-89			Lot	T	18	Black Cherry		Dead		Remove		HTM
RK358	Hartsville New Marlboro	AF	89-88			Lot	T	45	White Pine		Root decay		Remove		HTM
RK359	Hartsville New Marlboro		86-85			1059/1057	T	30	White Pine		Trunk and base decay		Remove		HTM
RK360	Hartsville New Marlboro	AF	82-81			Lot	T	9	White Pine		Trunk decay		Remove		HTM
RK368	Hartsville New Marlboro		11-10			Lot	T	32	Sugar Maple		Decline		Trim	remove front lead	HTM
RK373	New Marlborough Southfield		5-6			Lot	T	40	Maple		Base decay		Remove		HTM
RK374	New Marlborough Southfield		9-10			Lot	T	14	Stub		Dead		Remove		HTM
RK379	Mill River Southfield	AF	52-51			Lot	T	14	Ash		Decline		Remove		HTM
RK379	Mill River Southfield	AF	51-50			Lot	T	15	Pine		Dead		Remove		HTM
RK379	Mill River Southfield	AF	50-49			Lot	T	14	Black Cherry		Dead		Remove		HTM
RK379	Mill River Southfield	AF	50-49			Lot	T	10	Black Cherry		Dead		Remove		HTM
RK384	Mill River Southfield	AF	39-38			Lot	T	32	White Pine		Dead		Remove		HTM
RK385	Mill River Southfield	AF	37-36			Lot	T	14	Ash		Decline		Remove		HTM
RK386	Mill River Southfield		35-34.5			Lot	T	12	Oak		Buried in lines		Remove		HTM
RK387	Mill River Southfield	AF	30-29			Lot	T	36	Maple		Decline		Remove		HTM
RK387	Mill River Southfield	AF	30-29			Lot	T	28	Maple		Decline		Remove		HTM
RK387	Mill River Southfield	AF	30-29			Lot	T	20	Black Cherry		Decline		Remove		HTM
RK389	Mill River Southfield	AF	11-10			Lot	T	26	Sugar Maple		Decline/decay		Remove		HTM
RK390	Mill River Great Barrington		14-15			114	T	17	Black Cherry		Decline		Remove		HTM
RK398	Norfolk Rd.		9-10			460	T	40	Sugar Maple		Decay, decline TWR		Remove		HTM
RK399	Canaan Valley Rd	AF	31-32			Lot	T	16	Ash		Dead TWR		Remove		HTM
<b>Total Removals:</b>												<b>27</b>			
<b>Total Trims:</b>												<b>2</b>			